



# SERVICE BULLETIN

Classification: <b>BF93-049</b>	Section: <b>Body &amp; Frame</b>	Models: <b>All D21/WD21</b>
Reference: <b>TECHNICAL BULLETIN NTB93-186</b>	Date: <b>December 21, 1993</b>	

## DOOR MIRROR VIBRATION

**APPLIED MODELS:** All 1986-93 Truck (D21) and 1987-93 Pathfinder (WD21)

### SERVICE INFORMATION

Some Truck/Pathfinder vehicles may exhibit an abnormal vibration in the driver's door mirror. This incident may occur at normal highway speeds and the vibration may increase with speed.

Countermeasure door mirror assemblies (driver side only) have been developed to eliminate this incident if it occurs. If a vehicle manufactured within the applied dates below exhibits abnormal driver side door mirror vibration, replace it with the appropriate countermeasure mirror.

### PARTS INFORMATION

**Mirror Assy - Door, LH:**

New Part Number	Former Part Number	Applied Dates	
		D21	WD21
96302-07G60	96302-07G00	11/85 - 08/93	08/86 - 08/93
96302-57G60	96302-57G00	01/92 - 08/93	07/92 - 08/93
96302-92G60	96302-92G00	07/90 - 08/93	07/92 - 08/93
96302-57G70	96302-57G10	01/92 - 08/93	07/92 - 08/93
96302-11G70	96302-11G10	07/87 - 08/93	08/87 - 08/93
96302-11G20	96302-11G20	12/87 - 08/93	---

**WARRANTY INFORMATION\***

<b>Operation</b>	<b>Op Code</b>	<b>PNC</b>	<b>CS</b>	<b>CT</b>	<b>FRT</b>
Rpl one door mirror --manual or	UJ10AA	96301	4S	34	0.3 (all)
Rpl one door mirror -- electric	UJ10EA	96302	4S	34	0.3 (all)

\*Warranty information applies to those vehicles within the new vehicle warranty parameters for the particular model year. All others are "Goodwill" or at customer's expense.

**NISSAN MOTOR CORPORATION U.S.A.**  
Technical Publications Department