



INF

Handwritten notes: N → JA, T

NISSAN MOTOR CORPORATION IN U.S.A.

Post Office Box 191
Gardena, California 90248
Telephone: (310) 532-3111

TECHNICAL DATABASE INFORMATION

Record ID: FC0007788	Source Reference Number: FI75876	Classification: OCT '92
Subject: ENGINE NOISE	Entered On: 10/08/92	
Model Line: 720 M30 PTH MAX ZX	Model Year: 87 88 89 90 91 92	

Technical Information Abstract:

INFO SOURCE: STEVE, VAL STROUGH INFINITI, CA.

SYMPTOMS: KNOCKING NOISE HEARD AFTER TIMING BELT REPLACEMENT. SOUNDS LIKE A LIFTER OR ROD NOISE. ADJUSTED TENSION ACCORDING TO PROCEDURE IN SERVICE MANUAL, DURING INSTALLATION.

FIELD FIX: CHECK BELT TENSION & ADJUST. '90 & EARLIER S/M'S DO NOT SHOW 'BELT TENSION CHECK', '91 & LATER DO. SPECIFICATION IS 13-15MM (.51-.59 IN) DEFLECTION, WHEN PRESSING MIDWAY BETWEEN CAM SPROCKETS WITH A FORCE OF 10KG (22 LBS) (LOW END OF SPEC USED TO RESOLVE INCIDENT.)

Index * 031856